

A4 316 Equivalent Corrosion Resistance

- S-BT-ER M10/W10/15 SN 6 HL
- Hex Thin nut M10/W10-R
- Spring washer M10/W10-R
- Conductivity disc 120/AWG4/0

| | | |
|--|--|---------------|
| | SBT 4 | SBT 6 SF 6 |
| | TS-BT 5.3-65 S | |
| | TS-BT 5.3 HC | |
| | S-DG BT M10-W10/15 HC 6 | |
| | Torque Tool S-BT 1/4" 16 Nm / 11.8 lb-ft | |
| | S-NS P 1/4" HKH 17 (M10) S-NS 9/16" C 95/3 1/4" (W10) | |
| | S-CC BT HC 6 | |

1

SBT 4
SBT 6
SF 6

2

3

4

SBT 4 /
SBT 6 / SF 6

5

6

7

8

SBT 4
SBT 6
SF 6

9

10

1 click

11

12a

12b

3

10

12c

S-DG BT M10-W10/15 HC 6

12d

3

13

1x

2x

14

15a

8-16 Nm
5.9-11.8 ft-lb

15b

8-16 Nm
5.9-11.8 ft-lb

SBT 6

A4 316 Equivalent Corrosion Resistance

S-BT-ER M10/W10/15 SN 6 HL

- Hex Thin nut M10/W10-R
- Spring washer M10/W10-R
- Conductivity disc 120/AWG4/0

| | |
|--|--|
| | SBT 6 |
| | TS-BT 5.3-65 S |
| | TS-BT 5.3 HC |
| | S-SH BT M10/W10 |
| | Torque Tool S-BT 1/4" 16 Nm / 11.8 lb-ft |
| | S-NS 15 C 95/3 1/4" S-NS 9/16" C 95/3 1/4" |

1

SBT 6

2

>200 N
>45 lb

3

4

RPM 2000
200

5

6

SBT 6

7

8

9

10

click

SBT 6

11

12

13

14

15a

15b

16

17

18a

8-16 Nm
5.9-11.8 ft-lb

18b

8-16 Nm
5.9-11.8 ft-lb

SBT 6